

Description

Forklift safety labels, designed to reduce injury, remove risks and control dangerous situations surrounding forklift machinery.

Firstly, you need to be aware that under every cover and behind every guard there are moving parts. These moving parts on heavy machinery can cause harm with little effort.

Safety Labels warn and highlight the danger and risks involved in these situations.

Safety labelling crush zones, pinch points and the dangers surrounding forklifts is important.

This set of safety labels include danger labels for actions that could result in a fatality and warning labels for actions that can cause serious injury.

For more information relating to safety labels and stickers, contact Jaybro via phone or email.

Additional Information

CODE	41-100014
U.O.M	Pack

